## CENTRAL INTELLIGENCE AGENCY

## 410036

## INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

SECRET/CONTROL - U.S. OFFICIALS ONLY . HARORAL HOUSE

| COUNTRY        | Poland   | REPORT          |    | 25X′    |
|----------------|--|-----------------|----|---------|
| SUBJECT        | Gdynia Works! Council Criticism of Shipyard Conditions   | DATE DISTR.     | •  | ch 1954 |
|                |  | NO. OF PAGES    | 2  |         |
| DATE OF INFO.  |  | REQUIREMENT NO. | RD |         |
| PLACE ACQUIRED |  | REFERENCES      |    | 25X1    |
|                | This is UNEVALUATED Information  | n               |    |         |
|                | THE SOURCE EVALUATIONS IN THIS REPORT A THE APPRAISAL OF CONTENT IS TENT (FOR KEY SEE REVERSE) |                 |    |         |
|                |  |                 |    |         |

Below are several typical examples of articles, which appear in the wall news-sheet "Blyskawica" issued by the Works' Council of the Repair Shipyard in Gdynia. The bulletins mainly criticize the management of the shipyard as well as certain employees. It appears from this criticism that work is not being carried out in the yard as it should.

- Shipyard workers are not provided with suitable protective clothing, for instance, rubber boots have no soles.
- Only 50 percent of the production plan for July 1953 was completed.
- A powerful drilling machine, type Carlton, in the north workshop has been standing idle for seven months bacause the Central Administration of the Shipyard has forgotten its existence.
- Complaints about the dirt and the poor quality of meals in the shipyard canteen.
- Waste of non-ferrous metals.
- The shippard has transport trucks in stock but the workers are not using them because these trucks were not distributed among the work teconteand and consequently the internal ntransportation terms the nplant is poor.
- One of the workers completed his task pf painting a tank in seven hours instead of the planned 21 hours.
- In September 1953 the shippard received three trestle winches (windy kozlowe), a machine for making putty, and one circular saw. This reclimachinerylishlying in thedyand dod deterionsting.
- The workers are being exhorted to increased efforts in order to achieve the production target.

SECRET/CONTROL - U.S. OFFICIALS ONLY FB1 AEC

NAVY Washington Distribution Indicated By "X"; Field Distribution By "#".)

25 YEAR RE-REVIEW

ARMY

STATE

Approved For Release 2009/06/01 : CIA-RDP80-00810A003700710003-0

SECRET/CONTROL - U.S. OFFICIALS ONLY

- 2 -

25X1

j. The following units were in the #hipyard on 14 December 1953:

undergoing overhaul: SSS. BALTYK, TORUN and an unspecified number of fishing boats.

under construction:

three floating units.

SECRET/CONTROL - U.S. OFFICIALS ONLY